

Legend

- BL BOLLARD
- BS BUS STOP
- CATV CABLE TV COVER
- CL COVER LEVEL
- OPS CONCRETE PAVING SLAB
- DP DRAIN PIPE
- DR DROP KERB
- EL ELECTRICITY COVER
- EP ELECTRICITY POLE
- ER EARTH ROD
- FI FIRE HYDRANT
- FL FLOOR LEVEL
- FS FLAG STAFF
- G GAS COVER
- GLY GULLY
- GSV GAS STOP VALVE
- IC INSPECTION COVER
- IL INVERT LEVEL
- LB LITTER BIN
- LP LAMP POST
- MKR MARKER
- NB NOTICE BOARD
- P POST
- PH POST HOLE
- PIP PEDESTRIAN LAMP POST
- RR RODDING EYE
- RS ROAD SIGN
- SN SURVEY STATION
- STV STAY WIRE
- T TELECOMMUNICATIONS COVER
- TL TRAFFIC LIGHT
- TP TELEGRAPH POLE
- TML TOP OF WALL LEVEL
- U/L UNABLE TO LIFT
- U/M UNABLE TO MEASURE
- VP VENT PIPE
- WL WATER LEVEL
- WP WASTE PIPE
- WSV WATER STOP VALVE
- FENCE TYPES
- B/W BARBED WIRE
- C/B CLOSE BOARD
- P/W POST AND WIRE
- P/R POST AND RAIL
- C/L CHAIN LINK
- C/P CHESTNUT PALE
- C/W CHICKEN WIRE
- M/R METAL RAIL (SECURITY TYPE)
- P/E PANEL FENCE
- C/I CORRUGATED IRON
- I/R IRON RAILING
- RML RETAINING WALL

Notes

COPYRIGHT FOR DRAWING REMAINS WITH BUS LTD. AND MAY NOT BE COPIED WITHOUT THEIR WRITTEN CONSENT.

ANY SERVICES SHOWN ARE AS LOCATED BY EITHER GROUND PENETRATING RADAR (GPR) OR BY RADIO DETECTION SCANNER IN EITHER ACTIVE (A) OR PASSIVE MODE (P). DUE TO SUBSOIL CONDITIONS AND OTHER FACTORS, THE UNDERGROUND SERVICE INFORMATION SHOWN MAY NOT REPRESENT A COMPREHENSIVE RECORD AND ALL CONTRACTORS SHOULD PROCEED WITH CAUTION BEFORE EXCAVATION

\*\*\* DENOTES OVERHEAD CABLES  
 \* \* \* \* \* DENOTES UNDERGROUND SERVICES

LEVELS AT ROAD KERBS ARE TAKEN AT CHANNEL LEVELS UNLESS OTHERWISE INDICATED

STN	1	2	3	4	5
STN	1 E 362631820 N 363271348 H 1365228	2 E 362637180 N 363134468 H 1311716	3 E 362637180 N 363134468 H 1311716	4 E 362729400 N 363182188 H 1303246	5 E 362713234 N 363370995 H 1314989

BATTLEFIELD LAND SURVEYS LTD 11 LUDLOW ROAD BATTLEFIELD ENTERPRISE PARK SHREWSBURY SHROPSHIRE SY1 3EH TEL/FAX 01743 443388 EMAIL MAILBOX@LSURVEYS.CO.UK		Client COWER HOMES		Title PLAS ANEY RUTHIN ROAD, MOLD	
Scale	1 : 500	Date	23/03/2018	Job No	11203
Drawn by	Checked	Scanned	NO	Dwg No	1
Surveyed by	JS/DH	NO		Rev.	

